

职业卫生检测报告公示

用人单位名称	台州鑫恩塑业有限公司
地址	玉环市楚门镇彭宅村
联系人	高敏燕
项目组成人员	赖春华、祝琼燕、徐华超、陈煊真、应堡华
现场调查人员	徐华超、陈煊真
现场调查时间	2025.12.1
现场采样/检测人员	徐华超、陈煊真
现场采样/检测时间	2025.12.3
用人单位陪同人员	高敏燕
现场图像	 A photograph showing two individuals standing side-by-side in an indoor setting. The person on the left is wearing a yellow safety vest over a dark jacket and light-colored pants. The person on the right is wearing a white and black patterned coat and dark pants. They are positioned in front of a large display board featuring an advertisement for a product.  A photograph showing a person in a yellow safety vest operating a piece of industrial machinery. The machine has a blue frame and a control panel with a screen. A white dust collection bin is positioned nearby. Another person is visible in the background, working at a different station.